

VEHICLE INSPECTION REPORT

NL69ESV

Scania G 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 17/11/2019

VIN YS2G6X20005569896

Axle Combi 6x2

Year 2019

Body Style Tractor Unit

Steering Combi Mid-Lift

Mileage 774,292 Km Warranted

MOT Due 30/11/2025

Rear Suspension Air

Fuel Type Diesel

Cab Type NORMAL SLEEPER CAB

Colour WHITE

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Bluetooth connection
- Cruise control
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel Trim nsf
Scuffed
Over 25mm



6: Panel Rear
Dented
With Paint Damage



7: Door nsf
Dented
Over 30mm



8: Panel Front
Chipped
Multiple Chips



9: Door osf
 Scratched
 Over 25mm Thru Paint



10: Door Pad osf
 Soiled
 Heavy



11: Seat Base Cover osf
 Torn
 Over 3mm



12: Bumper Front Moulding
 Missing
 Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		