

VEHICLE INSPECTION REPORT

PK21CKP

Fiat Ducato Maxi 35 2.3 MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/05/2021

Year 2021

Mileage 96,310 Miles
Warranted

Fuel Type Diesel

Colour MULTI-COLOURED

VIN ZFA25000002P66564

Body Style Dropside

MOT Due 01/06/2026

CAP Clean £5,400.00

CAP Average £4,925.00

CAP Below £4,100.00

Gearbox MANUAL

Gears 6

Tail Lift Column

NO EXHAUST, WARNING LIGHT ON DASH AD-BLUE, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bonnet
Dented
With Paint Damage



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Broken
Replace



6: Door nsf
Chipped
Multiple Chips



7: Wing osf
Dented
With Paint Damage



8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		